



**APPENDIX J: DPS DESIGN ISSUES**

1. Drivers License: Money drawers too shallow. Deeper drawer violates ADA requirements. SOLUTION: Move drawer to side cabinet.
2. Entrances to Area Offices are confusing. SOLUTION: Proper signage or striping required.
3. Flag illumination. Violates light pollution statute but prohibits the flying of flag at night. SOLUTION: Variance.
4. Electrical and communications stub-ups. DPS prefers conduit stub-ups in lieu of j-boxes or raceways.
5. According to Andy Mokry 4/7/05, DPS has experienced problems with metal roofs.
6. DPS doesn't not like blanket roof insulation – access to equipment and securing insulation. SOLUTION:
7. Color Selection. DPS users are allowed to participate in color selections. SOLUTION: Personnel most likely to be at facility long term should participate. A/E should provide sufficient color boards for quick selection.
8. Minimum 9 ft. ceilings.
9. Drivers License – separate AC unit.
10. Parabolic fixtures not required.